



8	64100818000016	00	Tornillo M5 2	5	4.8 Purificación galvanizado		0.000		
7	64100097010086	00	Arandela 5	5	200HV purificación galvanizado		0.000		
6	64100093000028	00	Arandela 5	5	65Mn Purificación galvanizado		0.000		
5	60402000002463	00	Alero (II)	1	Placadeacero0195-12-GB/T11253-2007	0.770	0.770		
4	60402000001463	00	Alero (I)	1	Placadeacero0195-12-GB/T11253-2007	0.770	0.770		
3	60402400000463	00	Cubierta del freno de emergencia del alero delantero	1		2.421	2.421		
2	60402200000463	00	Composición del asa de la demarcación del alero	1		398.848	398.848		
1	60402100000463	00	Estructura de acero de la cabina del conductor	1		1505.096	1505.096		
S/N	PRODUCT NO.	V.	NAME	QT.	MATERIAL	PC.	TOT.	WT.	REMARKS
					WT.		SC.	CRRC ZIYANG LOCOMOTIVE CO., LTD.	
					1906.998		1:20	Montaje de la cabina del conductor y la sala de maquina delantera	
DSGN.	CHECKUP	STDZN.	VERIFIED	APPV.	TOT.SH.	SH.NO	6040200000463 00		V. SEC.CL